

	ストリート・スポーツ						GT-Specシリーズ			
	D300	D350	D400	D500	D700	D750	GT1	GT2	GT3	GT3LIMITED
	¥14,000	¥15,000	¥19,000	¥21,000	¥24,000	¥25,000	¥28,000	¥28,000	¥30,000	¥30,000
	¥17,000	¥18,000	¥22,000	¥24,000	¥27,000	¥28,000	¥31,000	¥31,000	¥33,000	¥33,000
	¥24,000	¥25,000	¥29,000	¥31,000	¥34,000	¥35,000	¥38,000	¥38,000	¥40,000	¥40,000
	¥28,000	¥29,000	¥33,000	¥35,000	¥38,000	¥39,000	¥42,000	¥42,000	¥44,000	¥44,000
	¥39,000	¥40,000	¥44,000	¥46,000	¥49,000	¥50,000	¥53,000	¥53,000	¥55,000	¥55,000
	¥28,000	¥30,000	¥38,000	¥42,000	¥48,000	¥50,000	¥56,000	¥56,000	¥60,000	¥60,000

車名	排気量	年式	型式・グレード	備考	フロント	リア		
WRX S4	2000	14.08~	VAG			FF16	RF18	
			VAG(ts)	brembo4POT		FF06	RF18	
WRX STI	2000	07.12~	GRB	brembo4POT/2POT		FF06	RF06	
		10.1~10.4	GRB(R205)	brembo6POT/4POT		FF60	RF60	
		10.7~	GVB	brembo4POT/2POT		FF06	RF06	
		10.7~17.6	VAB	brembo4POT/2POT		FF06	RF06	
		17.6~	VAB	brembo6POT/2POT		FF60	RF61	
	2500	09.2~	GRF(A-Line)	brembo		FF06	RF06	
		10.7~	GVF(A-Line)	brembo		FF16	RF16	
						FF06	RF06	
					FF16	RF16		
ディアス ワゴン DIAS WAGON	660	09.9~14.5	S321N			FD29	SD28	
			S331N			FD29	SD28	
	660	09.9~17.1	S321N			FD50	問合せ品番	
			S331N			FD50	問合せ品番	
	660	17.1~	S321N			FD52	問合せ品番	
		S331N			FD52	問合せ品番		
デックス DEX	1300	08.11~	M401F			FT19	ST03	
			M411F(4WD)			FT19	ST04	
トラヴィック TRAVIQ	2200	01.10~	HM200, XM220	REAR:BOSCH		FF15 *1	RF15	
				REAR:LUCAS		FF15 *1	RF17	
トレジア TREZIA	1300	10.11~14.4	NSP120X			FT35	ST41	
		14.4~	NSP120X			FT35	問合せ品番	
	1500	10.11~14.4	NCP120X			FT35	ST41	
		14.4~	NCP120X			TYPE EURO	FT35	RT90
						TYPE EURO	FT35	問合せ品番
		10.11~14.4	NCP125X			TYPE EURO	FT35	RT90
14.4~	NCP125X				FT35	ST41		
					FT35	問合せ品番		

1982	昭和	57
1983		58
1984		59
1985		60
1986		61
1987		62
1988		63
1989		64
1990	平成	2
1991		3
1992		4
1993		5
1994		6
1995		7
1996		8
1997		9
1998		10
1999		11
2000		12
2001		13
2002		14
2003		15
2004		16
2005		17
2006		18
2007		19
2008		20
2009		21
2010		22
2011		23
2012		24
2013		25
2014		26
2015		27
2016		28
2017		29
2018		30
2019		31
2020	令和	2
2021		3
2022		4

\*1 残量センサー取り付け部形状及びセンサー形状が変更されています。  
その為、残量センサー装着不可形状が有りますので、予めご了承ください。